

## Audi Cabriolet- roof fault guidance; technical tips; trim removal

2012-04-24 22:10:16 by audioc



There are a LOT of common issues with the Audi 80 based Cabriolet; thanks to the forum members, help is at hand

The following links should help with most common issues:

Audi Cabriolet - Fixing the electric/ hydraulic roof: <http://www.audifans.net/ftopic-29457.html>

Audi Cabriolet Faulty Roof code 01095: [www.audifans.net/ftopic-32228.html](http://www.audifans.net/ftopic-32228.html)

Audi Cabriolet Door Card Removal: [www.audifans.net/ftopic-14225.html](http://www.audifans.net/ftopic-14225.html)

Audi Cabriolet Rear Interior Side Trim Panel Removal: [www.audifans.net/ftopic-37326.html](http://www.audifans.net/ftopic-37326.html)

Audi Cabriolet Rear light panel removal/ refitting: [www.audifans.net/ftopic-31291.html](http://www.audifans.net/ftopic-31291.html)

More information (and banter/ discussion) can be found in the forum specifically for the Cabriolet- over and above the Audi 80/ 90/ Coupe: <http://www.audifans.net/forum-45.html>

<http://www.audifans.net/modules.php?name=News&file=article&sid=682>